


TJELDBEGGODEN - NORWAY



The capsulation of the work was crucial, as there were over 1,000 men working on site. Any leakage of blasting materials would have caused severe delays to the project. Despite subzero temperatures, we maintained the work areas to a minimum of 10°C.



The scaffolding was erected to the highest level of safety. The conditions were appalling, with high winds throughout the winter months, and on many occasions the equipment had to be dug out of the snow.